

Model: 520D XDR A
Vehicle identification number: WBA5J51030Dxxxxxx
Development code: F11
Model code: 5J61
Lead type: 5J61

Vehicle

BMW 520D XDR A, 135KW

WBA5J51030Dxxxxxx



Development code
Colour
Actual integration level
Start of warranty

F11
mineral-weiss metallic
F010-23-07-530
29 April 2014

Technical campaigns

There are no Campaigns for this vehicle.

VIN-based goodwill

Status	Campaign number	Description
Open	1SACC211056	Exhaust gas recirculation cooler Nx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

△ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live diagnosis



There are no service solutions for live diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscri...	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2014-1 (As of: 22-Mar-2024)	No valid subscription available.	-	Road Map EUROPE WEST Next 2024

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	520D XDR A
Body	TOUR
Vehicle identification number (last 7 digits)	DXXXXXX
Vehicle identification number (17 digits)	WBA5J51030DXXXXXX
Development code	F11
Steering	LL
Engine	N47T
Engine number	88638832
Exhaust re-treatment	EURO6,T, CI, M, N1 I
Transmission	AUT

Transmission number	0685909ZV0
Head unit serial number	HB2068E7843XXX
Drive	ALLR
Integration level, works	F010-14-03-502
Production date	17-Mar-2014
Production plant	Dingolfing
Delivery date	20-Mar-2014
Delivering retailer	Niederlassung Frankfurt, Frankfurt am Main, DE
National-market version	EUR
Paint code	A96
Upholstery code	LCSW
Model code	5J61
Basic type	5J51
Lead type	5J61

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0230 Extra package, EU-specific
 02K1 BMW LA wheel, V spoke 236
 02VB Tyre pressure display
 0316 automatic trunk lid mechanism
 0320 Deleted, model lettering
 0322 Comfort access
 0386 Roof railing
 03AC Trailer coupling
 03AG Reversing camera
 0417 Roller sun visor, rear door
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0494 Seat heating driver/passenger
 04B9 Interior trim strips,alum.finishgrinding

Retrofitted optional equipment:

This vehicle has no retrofits.

04NB Autom. climate control with 4-zone ctrl
04U2 Driving experience switch incl. ECO PRO
04UR Ambient interior light
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0524 Adaptive Headlights
0536 Auxiliary heating
0548 Kilometre speedo
0575 Additional 12V sockets
05AC High-beam assistant
0609 Navigation system Professional
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Comfort telephony w/ enhanced
Smartphone
06WA Instrument panel with extended scope
07XP Navigation package Connected Drive
0801 National version Germany
0851 Language version German
0879 On-board literature, German
08KA Oil service interval 24 mths / 30,000 km
08TF Active pedestrian protection
08TH Road sign detection
08V1 Information plate
09AA Outer skin protection
09BD Business Package
A105 105 Ah AGM battery
LEDE Leather equipment

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	22/03/2024	Warranty	144576 Km	02428	Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler Job: E84 F0x F1x F2x F3x N47T Replacing exhaust-gas recirculation

- Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Administrative effort	1 FRU
Flat rate unit I 00 74 758	

E84 Fx Gx Bx7 Nx7 Customer notification exhaust
gas recirculation cooler
Defect I 00 11 35 07 00

- Job: E84 F0x F1x F2x F3x N47T Replacing exhaust-gas recirculation cooler (high-temperature)

Description: E84 F0x F1x F2x F3x N47T Replacing exhaust-gas recirculation cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve	17 FRU
Flat rate unit I 00 72 953	

Additional work: run function test for pressure sensor system	3 FRU
Flat rate unit I 00 72 954	

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system	1 FRU
Flat rate unit I 00 72 955	

Additional work: clean exhaust gas recirculation pipe (not to be used when replacing intake system)	6 FRU
Flat rate unit I 00 72 956	

E84 F0x F1x F2x F3x N47T Replacing exhaust-gas
recirculation cooler (high-temperature)
Defect I 00 11 55 06 00

Exhaust gas cooler high temperature	1
Part I 11 71 7 822 350	

AGR small parts set	1
Part I 11 71 8 490 640	

Pipe union	2
Part I 11 71 7 799 853	

Holder
Part I 61 13 1 369 832

1

O-ring
Part I 11 61 8 512 681

1

Acoustic cover front
Part I 11 14 8 490 568

1

Pipe
Part I 13 71 7 810 772

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Defect I 85 40 00 26 SA

— 20/03/2024 Key

144566 Km

02428

Key 0




— 20/03/2024 Service

144566 Km

02428

Automatic

Bobrink&Co.
GmbH ,
Bremen



— 13/03/2023 Key

133626 Km

Key 0

 20000 06/2024	 20000 06/2024	 20000 06/2024	 20000 06/2024	 60000	 08/2023	 08/2023	 80000	 20000 06/2024
 07/2023		 07/2023						

— 13/03/2023 Repair 133626 Km 21735 Job
Bobrink &
Co. GmbH,
Osterholz-
Scharmbeck

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing left or right air
spring 10 FRU
Flat rate unit I 37 12 155

Luftfeder Local 1
Part I SP87 20 1 120 1

— 21/07/2022 Repair 126531 Km 21735 Job
Bobrink &
Co. GmbH, Job
Osterholz-
Scharmbeck

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing left or right tie rod end 6 FRU
Flat rate unit I 32 21 151

Kinematics Diagnosis System wheel alignment with
ride height measurement without loading the vehicle 24 FRU
Flat rate unit I 32 00 595

Left tie rod 1
Part I 32 10 6 784 716

Combination nut Part I 33 30 6 787 062	1
Hose clamp Part I 32 13 6 756 011	1
Pipe clamp Part I 32 10 6 791 548	1
Repair kit bellows Part I 32 10 6 791 561	1
Lubricating grease FB-1 Part I 83 23 8 849 305	1

— Job

Description:
Considered as a repeat visit No
Customer's own words

Pneumatic spring, rear Part I 37 10 6 784 379	1
--	---

— Job

Description:
Considered as a repeat visit No
Customer's own words

Ersatzfahrzeug Flat rate unit I LW	Local	1 FRU
---------------------------------------	-------	-------

16/06/2022

Key



30000

06/2024



30000

705



30000

705



30000

705



60000



08/2023



405



80000



30000

06/2024



07/2023




07/2023

125346 Km

Key 0

01/06/2022	Key	124756 Km	Key 0
------------	-----	-----------	-------



— 01/06/2022 Service 124756 Km 21735 Automatic
Bobrink&Co.
GmbH,
Osterholz-
Scharmbeck



— 01/06/2022 Repair 124756 Km 21735 Job
Bobrink & Job
Co. GmbH, Job
Osterholz- Job
Scharmbeck Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

ÖLFILTER	Local	1
Part I BO11 42 8 507 6		

Scheibenklar 0,5l	Local	2
Part I 99 99 4 000 000		

CASTROL Edge 5W-30	Local	5.2
Part I 83 21 2 405 950		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Microfilter service	3 FRU
Flat rate unit I 00 00 616	

SATZ MIKRO/AKTIVFILTER	Local	1
Part I BO64 11 9 272 6		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service fuel filter	5 FRU
Flat rate unit I 00 00 604	

KRAFTSTOFFFILTER	Local	1
Part I BO13 32 7 811 2		

Hose clamp	1
Part I 16 12 1 180 240	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service, front brakes	7 FRU
Flat rate unit I 00 00 612	

Removing and installing or replacing both front brake discs	2 FRU
Flat rate unit I 34 11 613	

Brake-pad paste Part I 83 19 2 158 851	2
Brake cleaner acetone-free Part I 83 19 2 413 695	1
Brake pad wear sensor, front left Part I 34 35 6 791 958	1
Repair kit, brake pads asbestos-free Part I 34 11 6 858 047	1
Brake disc, lightweight, ventilated Part I 34 11 6 896 652	2
Inner hex bolt Part I 34 21 1 161 806	2
Torx screw with washer Part I 34 10 6 864 424	4

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, Seasonal Check (only for German market) Flat rate unit I 00 00 101	7 FRU
--	-------

Service, Seasonal Check (only for German market) Flat rate unit I 00 00 101	0 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Balancing front and rear wheels stationary Flat rate unit I 36 10 568	7 FRU
--	-------

Balancing front and rear wheels stationary Flat rate unit I 36 10 568	0 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service Historie mittels ICOM ins Fahrze
Flat rate unit I 99 99 999

Local

1 FRU

— 01/06/2022 Repair 124756 Km 21735 Job
Bobrink &
Co. GmbH ,
Osterholz-
Scharmbeck

— Job

Description:

Considered as a repeat visit No

Customer's own words

Ersatzfahrzeug
Flat rate unit I LW


Local

1 FRU


— 12/05/2022 Key 124125 Km Remote
KeyRead




— 01/03/2022 Key 122066 Km Key 0



— 17/03/2020 Key 106365 Km Key 0



— 17/03/2020 Service 106365 Km 03910 Manual
 Autohaus
 Karl + Co.,
 Wiesbaden



— 17/03/2020 Repair 106366 Km 03910 Job
 Autohaus Job
 Karl + Co. Job
 GmbH & Job
 Co. KG, Job
 Wiesbaden Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope

2 FRU

Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service

3 FRU

Flat rate unit I 00 00 610

Motoröl 5W-30 Castrol Edge LL 04 1000 mltr. Part I FT83 21 0 398 5	Local	5.2
---	-------	-----

Set oil-filter element Part I 11 42 8 507 683		1
--	--	---

Windshield washer antifreeze Part I 83 12 2 468 609		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616		3 FRU
---	--	-------

Set, microfilter/carbon canister Part I 64 11 9 272 642		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602		1 FRU
--	--	-------

Air filter element Part I 13 71 7 800 151		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604		5 FRU
---	--	-------

Hose clamp Part I 07 12 9 952 104		1
--------------------------------------	--	---

Fuel filter cartridge Part I 13 32 7 811 227		1
---	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check 7 FRU
Flat rate unit I 00 00 624

— 29/08/2019 Key

99621 Km

Key 0

 8000 02/2020	 8000 184	 8000 184	 8000 184	 7000	 0 05/2021	 90000	 8000 02/2020
 0 06/2021	 0 06/2021						

— 29/08/2019 Repair

99621 Km

03910

Job

Autohaus
Karl + Co.
GmbH &
Co. KG,
Wiesbaden

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / maintenance 6 FRU
Flat rate unit I 00 99 000

Removing and installing/sealing or replacing oil feed
line for exhaust turbocharger 5 FRU
Flat rate unit I 11 42 200

Gasket ring 6
Part I 07 11 9 905 041

Hollow bolt 2
Part I 07 11 9 907 291

Oil pipe 1
Part I 11 42 7 808 756

Brake cleaner 2.0 1
Part I 83 19 2 365 214

— Job

Description:

Considered as a repeat visit No

Customer's own words

24-hour return service
Flat rate unit I 00 99 310

0 FRU

— 29/08/2019 Repair 99621 Km 26842 BMW J
Mobiler Service o
Einsatzleitzentrale b
, München


— Job

Description:

Considered as a repeat visit No

Customer's own words

— 24/06/2019 Key 96894 Km Key 0



— 24/06/2019 Repair 96894 Km 02756 Job
Niederlassung Job
Dreieich Job
BMW AG, Job
Dreieich Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Kunde bem.: zeitw. wird Leistungsreduzierung angezeigt prüfen und nach,Rücksp. inst.,

Performing vehicle test

4 FRU

Flat rate unit I 00 00 006

Vehicle diagnosis - carrying out the ABL

3 FRU

Flat rate unit I 61 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery

1 FRU

Flat rate unit I 61 21 528

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing/replacing exhaust turbocharger

14 FRU

Flat rate unit I 11 65 020

Additional work for visual check of exhaust turbocharger exchange

1 FRU

Flat rate unit I 11 65 508

RP Exhaust turbocharger

1

Part I 11 65 8 519 476

Exhaust turbocharger add-on kit

1

Part I 11 65 2 365 501

Preformed seal

1

Part I 13 71 8 596 850

— Job

Description:

Considered as a repeat visit No

Customer's own words Zu Job.4: Bei Heraus Schrauben des Drucksensor vor Kat wurde die, Schraube abgerissen., Die Schraube wurde bei festziehen abgerissen die Schraube wurde mit dem, Werkstattmeister erhitzt., Der Abgaskrümmer muss ausgebaut werden und dabei müssen die Stehbolzen, und Dichtung ersetzt werden.,

Additional work for exchange of exhaust turbocharger after vehicle diagnosis Flat rate unit I 11 65 505	5 FRU
Hose Part I 11 42 7 807 796	1
Set oil-filter element Part I 11 42 8 507 683	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
Oil pipe Part I 11 42 7 808 756	1
Hose clamp Part I 64 21 8 367 179	1
Gasket Steel Part I 11 62 8 509 783	2
Pipe, exhaust-gas pressure Part I 13 62 7 811 935	1
Hollow bolt Part I 13 62 7 811 933	1
Gasket ring Part I 13 62 7 811 934	2
ASA-stud bolt Part I 11 12 8 597 830	8
Flange nut Part I 11 62 8 597 827	8

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both gas pressure props for engine hood Flat rate unit I 51 23 766	1 FRU
---	-------

Gas pressure spring bonnet active Part I 51 23 7 309 117	2
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Presentation for emission inspection
Flat rate unit I 00 00 527

5 FRU

Überprüfung nach § 29 STVZO
Part I 0012159

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Serviceberatung am Fahrzeug
Part I 52050

Local

1

— Job

Description:


Considered as a repeat visit No

Customer's own words

— 13/05/2019 Key

95736 Km

Key 0



— 13/05/2019 Service

95736 Km

02756
Niederlassung
Frankfurt,
Dreieich

Manual



— 13/05/2019 Repair 95758 Km 02756 Job
 Niederlassung Job
 Dreieich Job
 BMW AG, Job
 Dreieich Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
 Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service 4 FRU
 Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
 Part I 83 13 2 184 843

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sommerräder montieren Winterräderdaten i Local 6 FRU
 Flat rate unit I AZ36 50 6

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service, rear brakes Flat rate unit I 00 00 614	8 FRU
--	-------

Repair kit, brake pads asbestos-free Part I 34 21 6 862 202	1
--	---

Brake-pad sensor, rear Part I 34 35 6 791 963	1
--	---

Brake-pad paste Part I 83 19 2 158 851	2
---	---

Safety cleaner 2.0 Part I 83 19 2 364 762	10
--	----

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words** Zu Pos.210: Index AGr-Kühler 823 210 06 Sichtprüfung
Kühlereintrittseite,wurden ABlagerungen festgestellt (siehe
Bilder),

Additional work for checking exhaust gas recirculation cooler label Flat rate unit I 00 67 708	1 FRU
--	-------

Vis. insp. of ex. gas rec. cooler cooler out. side; rep. ex. gas rec. cooler; clean mix. tube/ex. gas rec. pipe; func. check of press. sensor sys. Flat rate unit I 00 67 067	30 FRU
--	--------

Ersatzfahrzeug (24 Stunden) Part I 0000160	Local	1
---	-------	---

exhaust cooler Part I 11 71 8 476 993	1
--	---

EGR small parts set Part I 11 71 8 479 905	1
---	---

Pipe union
Part I 11 71 7 799 853

2

— 13/05/2019 Warranty 95758 Km 02756 Job: Exx Fxx Gxx Check exhaust-gas recirculation cooler and replace if needed

— Job: Exx Fxx Gxx Check exhaust-gas recirculation cooler and replace if needed

Description: Exx Fxx Gxx Check exhaust-gas recirculation cooler and replace if needed

Considered as a repeat visit No

Customer's own words

Additional work for checking exhaust gas recirculation cooler label
Flat rate unit I 00 67 708

1 FRU

Vis. insp. of ex. gas rec. cooler cooler out. side, rep. ex. gas rec. cooler; clean mix. tube/ex. gas rec. pipe; func. check of press. sensor sys.
Flat rate unit I 00 67 067

30 FRU

Exx Fxx Gxx Check exhaust-gas recirculation cooler and replace if needed
Defect I 00 11 97 04 00

exhaust cooler
Part I 11 71 8 476 993

1

AGR small parts set
Part I 11 71 8 479 905

1

Pipe union
Part I 11 71 7 799 853

2

— 30/11/2018 Warranty 90046 Km 02756 Job: SCR delivery module Permanent failure Job: Nitrogen oxide (NOx sensor) Permanent malfunction Job: Flexible disc on

propeller
shaft to rear
axle
differential
Cracked /
broken / torn
off

— Job: SCR delivery module Permanent failure

Description: SCR delivery module Permanent failure

Considered as a repeat visit No

Customer's own words

Replacing SCR active reservoir
Flat rate unit I 16 19 526

0 FRU

SCR delivery module Permanent failure
Defect I 16 19 02 12 00

SCR container
Part I 16 19 7 286 064

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace nitrogen oxide sensor downstream of SCR
catalytic converter
Flat rate unit I 13 62 622

0 FRU

Defect I 11 78 08 15 00

NOX sensor
Part I 13 62 8 589 846

1

— Job: Nitrogen oxide (NOx sensor) Permanent malfunction

Description: Nitrogen oxide (NOx sensor) Permanent malfunction

Considered as a repeat visit No

Customer's own words

Replacing nitrogen oxide sensor before SCR catalytic
converter
Flat rate unit I 13 62 620

0 FRU

Nitrogen oxide (NOx sensor) Permanent malfunction
Defect I 11 78 07 15 00

NOX sensor
Part I 13 62 8 589 846

1

— Job: Flexible disc on propeller shaft to rear axle differential Cracked / broken / torn off

Description: Flexible disc on propeller shaft to rear axle differential Cracked / broken / torn off

Considered as a repeat visit No

Customer's own words

Replacing flexible coupling for propeller shaft, rear
Flat rate unit I 26 11 521

0 FRU

Flexible disc on propeller shaft to rear axle differential
Cracked / broken / torn off
Defect I 26 11 02 01 00


Universal joint
Part I 26 11 7 610 061

1

— 27/11/2018 Key

90046 Km

Key 0



— 27/11/2018 Repair

90046 Km

02756
Niederlassung
Dreieich
BMW AG,
Dreieich
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Zu POS 50 27.11.18: Testmodul zu Stickoxidsensorik abgearbeitet,(Funktionstest) => beide Sensoren sind i.O. Modul

zu SCR Systemtest, gestartet in diesem wird die Funktionsprüfung am Dosiermodul mit, Mengenmessung durchgeführt => kein Druckaufbau möglich; nun soll das, Modul für das Dosiermodul abgearbeitet werden => Leckage- und, Leitungsprüfung am Bauteil waren i.O. bzw. keine Leckage ersichtlich., Te

stmodul zu Aktivtank bearbeitet => Leitungssprüfung mit, Widerstandsmessung vom Fördermodul und Rückfördermodul bzw. zum SCR, Steuergerät abgearbeitet (Unterbodenverkleidung HR und Abdeckboden, Kofferraum demontiert) => Widerstände und Spannungsversorgung sind i.O., 29.11.18: Testmodul zu SCR-Systemtest durchgeführt (Nach Ersatz von, Aktivtank) => NOx-Sensor vor Kat soll ers. werden anschließend, SCR-Systemtest erneut durchführen => NOx-Sensor nach SCR-Kat soll, getauscht werden anschließend SCR-Systemtest erneut durchführen., 30.11.18: Testmodul zu SCR-Systemtest durchgeführt => Der Test wurde, bestanden und es sind keine Fehler vorhanden => System i.O., *Keine Kontamination mit AD-Blue an allen Steckverbindungen, ersichtlich, *, Erschwernis beim Ausbau der Sensorik für Stickoxid vor Katalysator.,

Performing vehicle test Flat rate unit I 00 00 006		4 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006		57 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU
Job time without allowance for / fuel conditioning Flat rate unit I 13 99 000		3 FRU
Diesel Fluid AdBlue Part I 99 99 2 357 295	Local	19
Self-locking hex nut Part I 26 12 7 536 563		3
Base Part I 07 14 7 273 549		1
Hose clamp Part I 16 13 1 181 316		2
Hex Bolt Part I 26 11 7 527 475		3
Torx screw Part I 26 11 8 607 971		3
Cable strap, blue Part I 61 13 7 711 799		3

Cable tie	4
Part I 61 13 1 367 599	

Cable strap, blue	2
Part I 61 13 7 711 799	

Expanding nut	1
Part I 07 14 7 201 307	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Ersatzfahrzeug (24 Stunden)	Local	3
Part I 0000160		

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche	Local	1
Part I 0011319		

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Flüssigkeiten ergänzen : NEIN Kundenwuns	Local	1 FRU
Flat rate unit I NL00 00 3		

— Job

Description:

Considered as a repeat visit No

Customer's own words Kunde bem. im O-Ton: Motorkontrollleuchte leuchtet und ad blufe Fehler,wird im Controlldisplay angezeigt prüfen und nach Rücksp. inst.,

Replacing SCR active reservoir
Flat rate unit I 16 19 526

12 FRU

SCR reservoir
Part I 16 19 7 286 064

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Kunde bem. im O-Ton: Motorkontrollleuchte leuchtet und ad
blufe Fehler,wird im Controlldisplay angezeigt prüfen und nach
Rücksp. inst.,

Replace nitrogen oxide sensor downstream of SCR
catalytic converter
Flat rate unit I 13 62 622

3 FRU

NOx sensor
Part I 13 62 8 589 846

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Kunde bem. im O-Ton: Motorkontrollleuchte leuchtet und ad
blufe Fehler,wird im Controlldisplay angezeigt prüfen und nach
Rücksp. inst.,

Replacing nitrogen oxide sensor before SCR catalytic
converter
Flat rate unit I 13 62 620

6 FRU

NOx sensor
Part I 13 62 8 589 846

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Kunde bem.: Hardyscheibe hinten gerissen im Rahmen der
Serviceberatung,fest gestellt.,

Replacing flexible coupling for propeller shaft, rear
Flat rate unit I 26 11 521

20 FRU

Universal joint
Part I 26 11 7 610 061

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Serviceberatung am Fahrzeug
Part I 52050

Local

1

— Job

Description:


Considered as a repeat visit No

Customer's own words

— 30/05/2018 Key

83329 Km

Key 0



— 26/02/2018 Key

80691 Km

Key 0





— 26/02/2018 Service

80691 Km

02756
Niederlassung
Frankfurt,
Dreieich

Manual





— 26/02/2018 Repair 80691 Km 02756 Job
Niederlassung Job
Dreieich Job
BMW AG, Job
Dreieich Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11 42 8 507 683

BMW Engine Oil LL04 0W30 5
Part I 83 21 2 405 950

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 3 FRU
Flat rate unit I 00 00 616

Set, microfilter/carbon canister 1
Part I 64 11 9 272 642

— Job

Description:

Considered as a repeat visit No

Customer's own words

Flüssigkeitsstände prüfen ggf. ergänzen:
Flat rate unit I AZ00 54 2 Local 1 FRU

Windshield washer antifreeze
Part I 83 12 2 409 031 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW
Flat rate unit I IM00 25 0 Local 2 FRU

— Job


Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche
Part I 0011319 Local 1

— 23/02/2018 Key 78757 Km Key 0



— 04/10/2017 Repair 123 Km 00086 Job
Niederlassung
Kassel BMW
AG, Kassel

— Job

Description:

Considered as a repeat visit No

Customer's own words

9051I, 1732861757
Part I 0000156


Local

1

— 21/08/2017 Key

73678 Km

Key 0



— 21/08/2017 Repair

73678 Km

02756 Job
Niederlassung Job
Dreieich Job
BMW AG, Job
Dreieich

— Job

Description:

Considered as a repeat visit No

Customer's own words

Repair kit, rotary actuator
Part I 61 31 9 393 931

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Handle, floor carpet-luggage comp
Part I 51 47 7 267 484

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

GA-Reklamation (nur Dreieich)
Flat rate unit I AZ00 06 0

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words Fzg nicht waschen.,

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU


— 20/07/2017 Service

72967 Km

02756

Manual








Niederlassung
Frankfurt,
Dreieich



— 19/07/2017 Key

72967 Km









Key 0



— 19/07/2017 Key

72960 Km

Key 0



— 19/07/2017 Repair

72967 Km

02756

Job

Niederlassung Job

Dreieich Job

BMW AG, Job

Dreieich Job

Job

Job

Job

Job

Job

Job

Job

Job

Job

Job

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Überprüfung nach § 29 STVZO
Part I 0012159

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Exhaust emission inspection with OBD
Flat rate unit I 00 00 128

3 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words Fzg. Check zurücksetzen.,

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Windshield washer antifreeze
Part I 83 12 2 409 031

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: TÜV SÜD bemängelt: Fehlerspeicher KAFAS und Potentiometer des, Schichtungssteller vor inst. Rückspr.,

Vehicle diagnosis - carrying out the ABL	1 FRU
Flat rate unit I 61 00 006	

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: Laut SPS:Bei PF ist die Motorkontrolllampe angegangen, Leistungsverlust, vor inst. Rückspr., Im Fehlerspeicher war kein Fehler zur DDE gespeichert. Fehlerspeicher, wurde bei der 72. Pkt. Durchsicht bereinigt gelöscht. Anhand der Schlüssel- und Daten ist aber deutlich zu erkennen, dass das AGR-Ventil auffällig ist. Aus Erfahrungswerten und im Zuge der Kundenzufriedenheit, wird das AGR-Ventil ersetzt und im Anschluss wird das Fzg. mit einer neuen Software programmiert., 19.07.2017, Claudio Latino, Testmodul KAFAS Kamera Fehler Beheizung Sichtprüfung der Steck-, Verbindung festgestellt Stecker An der Frontscheibe nicht korrekt aufgesteckt,

Performing vehicle test	3 FRU
Flat rate unit I 00 00 556	

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
Flat rate unit I 61 21 528	

Troubleshooting electrical/electronic system	1 FRU
Flat rate unit I 61 00 009	

Replacing exhaust gas recirculation valve	4 FRU
Flat rate unit I 11 71 501	

Programming/encoding control unit(s) including deleting fault memories	4 FRU
Flat rate unit I 61 00 730	

Install and remove KAFAS camera	2 FRU
Flat rate unit I 66 51 530	

EGR-valve	1
Part I 11 71 7 810 871	

Hose clamp	4
------------	---

Oval head screw
Part I 35 21 7 685 343

2

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: TÜV SÜD bemängelt;

Hinweisschild Fanghaken erneuern, fehlt.
Flat rate unit I AZ51 99 0

Local

1 FRU

Information plate, retaining hook
Part I 71 21 7 209 617

1

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: TÜV SÜD bemängelt;

Deckel Stützpunkt B+ Motorraum erneuern,
Flat rate unit I AZ61 99 0

Local

1 FRU

B+ terminal point cover, eng. compart.
Part I 61 14 9 192 666

1

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: TÜV SÜD bemängelt;

Tankverschluss erneuern.
Flat rate unit I AZ16 99 0

Local

1 FRU

Filler cap
Part I 16 11 7 222 392

1

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: TÜV SÜD bemängelt:Staulippenverkleidungen vorn links
undrechts erneuern, gebrochen.,

Removing and installing/replacing front left or right
wheel arch cover
Flat rate unit I 51 71 538

4 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing/replacing front left or right wheel arch cover Flat rate unit I 51 71 538	4 FRU
--	-------

Cover, bottom right Part I 51 75 7 312 830	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: TÜV SÜD bemängelt:, Unterbodenverkleidung links ersetzen,

beschädigte Unterbodenverkleidungen erne Flat rate unit I AZ51 99 0	Local	1 FRU
--	-------	-------

Remove and install/replace left or right underbody panelling Flat rate unit I 51 71 515	3 FRU
--	-------

Removing and installing/replacing front and rear underbody protection Flat rate unit I 51 47 995	5 FRU
---	-------

Underfloor coating center Part I 51 75 7 186 714	1
---	---

Underbody panelling, left Part I 51 75 7 207 267	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words *E: TÜV SÜD bemängelt: Schloß für Ablagefach Mittelkonsole klemmt, vor inst: Rückspr.,

Removing and installing or replacing centre armrest latch
Flat rate unit I 51 16 773 4 FRU

Rep.kit f lock cylinder
Part I 51 16 9 202 265 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz gebraucht Detail APZ
Part I 99 01 0 000 001 Local 1

— Job

Description:

Considered as a repeat visit No

Customer's own words


BMW key ring Square
Part I 80 56 0 443 278 1


— Job

Description:

Considered as a repeat visit No

Customer's own words





— 05/04/2017 Service

70515 Km

32320 Automatic
ASW
Wahl
GmbH
&
Co.KG,
Gießen



— 05/04/2017 Repair

70515 Km

32320 Job
Alfred Job
Wahl Job
GmbH
& Co.
KG ,
Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Additional work, top up AdBlue
Flat rate unit I 00 00 667

2 FRU

Diesel Exhaust Fluid AdBlue 1000ML, TU
Part I FT99 19 2 289 6

Local

9

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash and interior vehicle cleaning
Flat rate unit I 00 11 329

0 FRU

— 05/04/2017 Warranty

70515 Km

32320

Job: F0x F1x
N47 B47
Replace air
conditioning
condenser

— Job: F0x F1x N47 B47 Replace air conditioning condenser

Description: F0x F1x N47 B47 Replace air conditioning condenser

Considered as a repeat visit No

Customer's own words

Check and replace air conditioning capacitor
Flat rate unit I 00 64 293

17 FRU

F0x F1x N47 B47 Replace air conditioning condenser
Defect I 00 64 93 01 00

Condenser air conditioning
Part I 64 50 9 391 489

1

Hex bolt
Part I 07 14 7 029 829

2

Gasket ring
Part I 64 50 8 375 741

1


Gasket ring

1

— 04/04/2017 Key

70076 Km

Key 0



— 09/03/2017 Key

68573 Km


~~Key 0~~



— 24/11/2016 Key

63078 Km

Key 0



— 24/11/2016 Repair

63078 Km

32320
Alfred
Wahl
GmbH
& Co.
KG,
Gießen

Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check Ablaufdatum Verbandskasten (06 / Local 1 FRU
19)
Flat rate unit I 00 52 000

— Job

Description:

Considered as a repeat visit No

Customer's own words


Additional work, top up AdBlue 2 FRU
Flat rate unit I 00 00 667


Diesel Exhaust Fluid AdBlue 1000ML, TU Local 11
Part I FT99 19 2 289 6

— 28/07/2016 Key 53518 Km Key 0



— 28/07/2016 Service 53518 Km 32320 Manual
ASW
Wahl
GmbH
& Co.
KG,
Gießen





— 28/07/2016 Repair

53518 Km

32320 Job
Alfred Job
Wahl Job
GmbH Job
& Co. Job
KG, Job
Gießen Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check 7 FRU
Flat rate unit I 00 00 624

Windshield washer antifreeze 2
Part I 83 12 2 296 208

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Castrol Edge ProfessionalLL04 0W-30 Local 5.2
Part I FT97 99 0 000 0

Set oil-filter element 1
Part I 11 42 8 507 683

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 3 FRU
Flat rate unit I 00 00 616

Set, microfilter/carbon canister
Part I 64 11 9 272 642

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	1 FRU
--	-------

Air filter element Part I 13 71 7 800 151	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	5 FRU
---	-------

Fuel filter cartridge Part I 13 32 7 811 227	1
---	---

Hose clamp Part I 07 12 9 952 104	1
--------------------------------------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes Flat rate unit I 00 00 612	7 FRU
---	-------

Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 11 6 858 047	1
--	---

Brake pad wear sensor, front left Part I 34 35 6 791 958	1
---	---

Retaining clip Part I 34 35 6 787 325	1
--	---

Brake-pad paste	2
-----------------	---

Part I 83 19 2 158 851

Brake disc, lightweight, ventilated
Part I 34 11 6 794 429

2

Inner hex bolt
Part I 34 21 1 161 806

2

Hex Bolt
Part I 34 11 6 772 117

4

— Job

Description:

Considered as a repeat visit No

Customer's own words

Wagenoberwäsche , Fussraum saugen, Motorwäsche
oberhalb OHNE BERECHNUNG
Flat rate unit I 00 11 330

0 FRU

— 15/06/2016 Key

49387 Km

Key 0



— 15/06/2016 Repair

49387 Km

32320

Job

Alfred
Wahl
GmbH
& Co.
KG ,
Gießen

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Reinigung zum Schnellservice * Frontscheibe
reinigen * Fußraum vorne aussaugen
Flat rate unit I 00 52 900

Local

1 FRU

Quick service with compact check or service
consultation at vehicle
Flat rate unit I 00 52 055

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Additional work, top up AdBlue	2 FRU
Flat rate unit I 00 00 667	

Diesel Exhaust Fluid AdBlue 1000ML, TU	Local	11
Part I FT99 19 2 289 6		

— 01/12/2015 Repair 36707 Km 32320 Job
Alfred Job
Wahl Job
GmbH Job
& Co. Job
KG,
Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check	Local	-1 FRU
Flat rate unit I 00 52 000		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Additional work, top up AdBlue	-2 FRU
Flat rate unit I 00 00 667	

Diesel Exhaust Fluid AdBlue 1000ML, TU	Local	-7
Part I FT99 19 2 289 6		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Scheibenklar mit Frostschutz auffüllen JA (x) NEIN () Local
Flat rate unit I 00 00 246

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölstand prüfen, ggf. ergänzen JA (x) NEIN () Local
Flat rate unit I 00 00 247

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words


Windshield washer antifreeze
Part I 83 12 2 296 208

-2

— 18/11/2015 Key

36707 Km

Key 0



— 18/11/2015 Repair

36707 Km

32320 Job
Alfred Job
Wahl Job
GmbH Job
& Co. Job
KG ,
Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check Flat rate unit I 00 52 000	Local	1 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Additional work, top up AdBlue Flat rate unit I 00 00 667		2 FRU
--	--	-------

Diesel Exhaust Fluid AdBlue 1000ML, TU Part I FT99 19 2 289 6	Local	7
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Scheibenklar mit Frostschutz auffüllen JA (x) NEIN () Flat rate unit I 00 00 246	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölstand prüfen, ggf. ergänzen JA (x) NEIN () Flat rate unit I 00 00 247	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Windshield washer antifreeze Part I 83 12 2 296 208		2
--	--	---

—	18/11/2015	Repair	36707 Km	32320	Job
				Alfred	Job
				Wahl	Job
				GmbH	Job
				& Co.	
				KG ,	
				Gießen	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check Flat rate unit I 00 52 000	Local	1 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Additional work, top up AdBlue Flat rate unit I 00 00 667		2 FRU
--	--	-------

Diesel Exhaust Fluid AdBlue 1000ML, TU Part I FT99 19 2 289 6	Local	7
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Scheibenklar mit Frostschutz auffüllen JA (x) NEIN () Flat rate unit I 00 00 246	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölstand prüfen, ggf. ergänzen JA (x) NEIN () Flat rate unit I 00 00 247	Local	0 FRU
--	-------	-------

Windshield washer antifreeze Part I 83 12 2 296 208		2
--	--	---

—	22/06/2015	Repair	26295 Km	32320	Job
				Alfred	Job
				Wahl	Job
				GmbH	Job
				& Co.	Job
				KG ,	
				Gießen	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	-2 FRU
Flat rate unit I 00 00 105	

Additional work, top up AdBlue	-2 FRU
Flat rate unit I 00 00 667	

Diesel Exhaust Fluid AdBlue 1000ML, TU	Local	-8
Part I FT99 19 2 289 6		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	-3 FRU
Flat rate unit I 00 00 610	

CASTROL EDGE PROFESSIONALBMW LL04 0W-30	Local	-5.2
Part I FT91 99 6 005 2		

Set oil-filter element	-1	
Part I 11 42 8 507 683		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	-3 FRU
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	-1	
Part I 64 11 9 272 642		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check	Local	-1 FRU
Flat rate unit I 00 52 000		

Scheibenklar auffüllen JA (X) NEIN ()
Flat rate unit I 00 00 246

Local

0 FRU

Windshield washer antifreeze
Part I 83 12 2 296 208

-2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash and interior vehicle cleaning
Flat rate unit I 00 11 329

0 FRU

— 08/06/2015 Service

26295 Km 32320 Manual
ASW
Wahl
GmbH
& Co.
KG,
Gießen



— 08/06/2015 Repair

26295 Km 32320 Job
Alfred Job
Wahl Job
GmbH Job
& Co. Job
KG ,
Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Additional work, top up AdBlue		2 FRU
Flat rate unit I 00 00 667		

Diesel Exhaust Fluid AdBlue 1000ML, TU	Local	8
Part I FT99 19 2 289 6		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service		3 FRU
Flat rate unit I 00 00 610		

CASTROL EDGE PROFESSIONALBMW LL04 0W- 30	Local	5.2
Part I FT91 99 6 005 2		

Set oil-filter element		1
Part I 11 42 8 507 683		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service		3 FRU
Flat rate unit I 00 00 616		

Set, microfilter/carbon canister		1
Part I 64 11 9 272 642		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check	Local	1 FRU
Flat rate unit I 00 52 000		

Scheibenklar auffüllen JA (X) NEIN ()	Local	0 FRU
Flat rate unit I 00 00 246		

Windshield washer antifreeze		2
Part I 83 12 2 296 208		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash and interior vehicle cleaning 0 FRU
Flat rate unit I 00 11 329

— 08/06/2015 Repair 26295 Km 32320 Job
Alfred Job
Wahl Job
GmbH Job
& Co. Job
KG ,
Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Additional work, top up AdBlue 2 FRU
Flat rate unit I 00 00 667

Diesel Exhaust Fluid AdBlue 1000ML, TU Local 8
Part I FT99 19 2 289 6

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
Flat rate unit I 00 00 610

CASTROL EDGE PROFESSIONALBMW LL04 0W- Local 5.2
30
Part I FT91 99 6 005 2

Set oil-filter element 1
Part I 11 42 8 507 683

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 3 FRU

Flat rate unit I 00 00 616

Set, microfilter/carbon canister
Part I 64 11 9 272 642

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check
Flat rate unit I 00 52 000

Local

1 FRU

Scheibenklar auffüllen JA (X) NEIN ()
Flat rate unit I 00 00 246

Local

0 FRU

Windshield washer antifreeze
Part I 83 12 2 296 208

2

— Job

Description:








Considered as a repeat visit No

Customer's own words









Vehicle surface wash and interior vehicle cleaning
Flat rate unit I 00 11 329


0 FRU

— 01/06/2015 Key 23300 Km Key 0



— 02/01/2015 Key 17564 Km 32320 Key 0





— 02/01/2015 Repair

17564 Km

32320 Job
Alfred Job
Wahl
GmbH
& Co.
KG ,
Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Additional work, top up AdBlue
Flat rate unit I 00 00 667

2 FRU

Diesel Exhaust Fluid AdBlue 1000ML, TU
Part I FT99192289602

Local

14

— Job

Description:

Considered as a repeat visit No

Customer's own words FS

— 10/11/2014 Repair

14295 Km

32320 Job
Alfred Job
Wahl Job
GmbH Job
& Co. Job
KG , Job
Gießen Job

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Räder montieren Flat rate unit I AZ01 02 1	Local	-6 FRU
---	-------	--------

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Rädereinlagerung inkl. Maschinenreinigung Flat rate unit I AZ01 02 4	Local	-1 FRU
---	-------	--------

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Kompakt-Check Flat rate unit I 00 52 000	Local	-1 FRU
---	-------	--------

— Job

Description:

Considered as a repeat visit No

Customer's own words pg

Scheibenklar auffüllen JA () NEIN () Flat rate unit I 00 00 246	Local	0 FRU
--	-------	-------

Windshield washer antifreeze Part I 83 12 2 296 208		-1
--	--	----

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Motorölstand prüfen, ggf. ergänzen Ja () Nein () Flat rate unit I 00 00 247	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Reinigung zum Schnellservice * Frontscheibe
reinigen * Fußraum vorne aussaugen
Flat rate unit I 00 52 900

Local

-1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words Gutschrift, Abrechnung über AudaCon Watchneue Rg #
118141-14, ak

— 06/11/2014 Repair

14295 Km

32320 Job

Alfred Job

Wahl Job

GmbH Job

& Co. Job

KG, Job

Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Räder montieren

Local

6 FRU

Flat rate unit I AZ01 02 1

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Rädereinlagerung inkl. Maschinenreinigung

Local

1 FRU

Flat rate unit I AZ01 02 4

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Kompakt-Check

Local

1 FRU

Flat rate unit I 00 52 000

— Job

Description:

Considered as a repeat visit No

Customer's own words pg

Scheibenklar auffüllen JA () NEIN ()	Local	0 FRU
Flat rate unit I 00 00 246		

Windshield washer antifreeze		1
Part I 83 12 2 296 208		

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Motorölstand prüfen, ggf. ergänzen Ja () Nein ()	Local	0 FRU
Flat rate unit I 00 00 247		

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Reinigung zum Schnellservice * Frontscheibe reinigen * Fußraum vorne aussaugen	Local	1 FRU
Flat rate unit I 00 52 900		

—	06/11/2014	Repair	14295 Km	32320	Job
				Alfred	Job
				Wahl	Job
				GmbH	Job
				& Co.	
				KG ,	
				Gießen	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check	Local	1 FRU
Flat rate unit I 00 52 000		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Scheibenklar auffüllen JA () NEIN ()
Flat rate unit I 00 00 246

Local

0 FRU

Windshield washer antifreeze
Part I 83 12 2 296 208

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölstand prüfen, ggf. ergänzen Ja () Nein ()
Flat rate unit I 00 00 247

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Reinigung zum Schnellservice * Frontscheibe
reinigen * Fußraum vorne aussaugen
Flat rate unit I 00 52 900

Local

1 FRU

— 06/11/2014 Warranty

14295 Km

32320

Job: F11
Replace
loading edge
trim

— Job: F11 Replace loading edge trim

Description: F11 Replace loading edge trim

Considered as a repeat visit No

Customer's own words

Rep. insert positioner for load.ed. trim
Flat rate unit I 00 62 816

3 FRU

F11 Replace loading edge trim
Defect I 00 51 53 03 00

Set of inserts
Part I 51 47 7 275 087

1

— 12/09/2014 Key

9349 Km

Key 0

 16000 03/2016	 0	 16000 566	 0	 30000	 0 03/2017	 42000	 41000 03/2018
 0 04/2017	 0 04/2017						

— 12/09/2014 Repair 9349 Km 00086 Job
Niederlassung Job
Kassel BMW Job
AG, Kassel Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words ** Stoßfänger hinten und AHK wurde ersetzt
*****, #129;RDC-SG
wird von Diagnose nicht erkannt-> Versorgung laut
Ablauf, geprüft=Sicherung i.O. Stecker nicht am Steue
rgerät angeschlossen., Abschließend Luftdrücke eingestellt
(normale Beladung laut KD-Wunsch), und System resetet-> kein
weitere RDC-Fehler gespeichert., ! Festpos. RDC-SG a+e in der
AZ!!,

Performing vehicle test	4 FRU
Flat rate unit I 00 00 006	

Vehicle diagnosis - carrying out the ABL	2 FRU
Flat rate unit I 61 00 006	

Removing and installing RDC control unit	3 FRU
Flat rate unit I 36 11 519	

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle check in course of reception
Flat rate unit I 00 52 054

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words Fahrzeugdiagnose-Testmodul- durchführen,#Most
Konfiguration nicht gespeichert.,#129;MOST-konfiguration
nicht in der Headunit gespeichert.,Ablaufplan abgearbeitet und
Konfiguration über Servicefunkti
on,geschrieben.,Abschließend erneut geprüft=i.O.,Bef.
6577411400,

Vehicle diagnosis - carrying out the ABL
Flat rate unit I 61 00 006

1 FRU

— 12/09/2014 Warranty

9349 Km

00086

Job: Central
gateway
module
(ZGM/ZGW)
Occasional
malfunction

— Job: Central gateway module (ZGM/ZGW) Occasional malfunction

Description: Central gateway module (ZGM/ZGW) Occasional malfunction

Considered as a repeat visit No

Customer's own words

Vehicle diagnosis - carrying out the ABL
Flat rate unit I 61 00 006

1 FRU

Central gateway module (ZGM/ZGW) Occasional
malfunction
Defect I 65 77 41 14 00

— 08/05/2014 Repair

0 Km

32320

Job

Alfred
Wahl
GmbH
& Co.
KG,
Gießen

— Job

Description:

Considered as a repeat visit No

Customer's own words NEUEINLAGERUNG

Rädereinlagerung inkl. Maschinenreinigung
Flat rate unit I AZ01 02 4

Local

1 FRU

<https://bmwcheck.eu>
EXAMPLE